

General safety instructions for visitors



**We warmly welcome you to our headquarters,
Albstraße 49, 72525 Münsingen**

**Phone: +49 7381 – 186 – 0 (Headquarters)
+49 7381 – 186 – 86 (Operations management)**

Please note:

Genkinger GmbH is committed to the highest possible safety, including for its visitors. For your own safety, please follow the instructions of our staff who are looking after you and adhere to the following safety rules and instructions..

The “UVV” (accident prevention regulations) of the “BGHM” (Professional Association for Wood and Metal) apply in our factory, which you can view on the BGHM website.

By signing the visitor list, you confirm that you have read and understood the safety rules.

Please familiarize yourself with the escape routes and rescue routes.

Please wear a high-visibility vest during guided tours and do not leave the group under any circumstances. Maintain a safe distance from running machinery and grinding and welding activities.

Only tested electrical equipment may be used in our company.

The premises are under video surveillance



Factory traffic:

The German Road Traffic Act (StVo) applies on our premises. The maximum speed is 10 km/h. Parked vehicles may not block the flow of traffic or access to safety device. Please park in the assigned or marked parking spaces.



Safety and warning information:

For your own safety and to protect your health, please wear the appropriate protective equipment in the marked work areas.



Safety shoes



Safety glasses



Hearing protection

Smoking and the consumption of alcohol and drugs are prohibited on our premises. Photography and sound recordings are not permitted.



Access to designated areas is prohibited for unauthorized persons:



Please do not touch any tools, parts, machines, or equipment. There is a risk of injury and health hazards due to contact with operating fluids and static electricity.



People with pacemakers and implants should stay away from designated areas:



Warning against internal transport with industrial trucks. Particular caution is required at intersections and areas with poor visibility.



Warning: Suspended loads. Particular caution is required during internal transport by crane. Standing beneath suspended loads is prohibited.



Avoid looking directly into the welding arc. There is a risk of eye burns.



In operating areas marked with this warning sign (warning of explosive atmosphere) or in the building surroundings, additional regulations and rules of conduct must be observed.

In potentially explosive atmospheres, it is strictly prohibited for anyone to carry or use equipment that could become an ignition source.

Work involving ignition hazards is only permitted with an appropriate permit.



What to do in an emergency:

**Please remain calm and inform the staff member caring for you.
If this is not possible, call the emergency number **112**.**

Important information in the event of an accident:

**Where did it happen?
What happened?
How many were injured?
What injuries?
Waiting for follow-up questions.**



In case of fire:

**Follow the escape route signs and go to the assembly point
in front of the main administration building (near reception).**

